


1



1x [Panel]

1x [Bracket]

2x [Panel]

4x [Bracket]

4x [Pin]

24x [Screw]

4x [Pin]

4x [Cap]

4x [Cap]

5x [Screw]

2




Diagram showing the attachment of the top panel to the side panels. Callouts 1, 2, 3, 4, and 5 indicate the placement of pins, caps, and screws.

3




Diagram showing the attachment of the bottom panel to the side panels. A circular inset provides a detailed view of the corner joint assembly.

4




Diagram showing the final assembled table structure.